

# General Environmental Incident Summary

**Incident:** 1908      **Date/Time Notice:** 4/23/2013      0915      **DEM Incident No:**  
**Responsible Party:** Southern Energy Transportation, LLC  
**Date Incident:** 4/22/2013      **Time Incident:** 16:03      **Duration:** 1 minutes  
**County:** Mountrail      **Twp:** 153      **Rng:** 91      **Sec:** 27      **Qtr:** NW NW NW  
**Lat:** 48.04485      **Long:** -102.36430      **Method:** Derived from TRS  
**Location Description:** Liffbrig 11-27H. Highway 8 north to 43rd street , west 2 miles to 82nd street, right on 44th street. 1/2 mile stay right to well.

**Submitted By:** David LaMay      **Affiliation:**

**Address:**

**City:**      **State:**      **Zip:**

**Received By:**

**Contact Person:** Otis Randle  
800 Spring St, suite 205  
Shreveport, LA 71101

**Distance Nearest Occupied Building:** 1 Miles

**Type of Incident:** trailer overflowed

**Description of Released Contaminant:** Crude Oil

**Volume Spilled:** 5.00 gallons      **Ag Related:** No

**EPA Extremely Hazardous Substance:** Unknown      **Reported to NRC:** Unknown

**Cause of Incident:**

Driver forgot to open valve to the next compartment in his trailer and backed up oil into the vent line and oil then ran out vent hose.

**Risk Evaluation:**

None

**# of Fatalities:** 0      **# of Injuries:** 0      **Affected Medium:** 03 - soil

**Potential Environmental Impacts:**

No water nearby spill, oil was absorbed immediately and contaminated soil disposed of.

**Action Taken or Planned:**

Stopped the oil flow. Called in the spill to the dispatcher at 4:03pm. Robert Reed arrived on site and assisted the driver with clean up. They cleaned it up with diapers and absorbent pads from 4 truck spill kits.

**Wastes Disposal Location:** It was disposed of into Whiting Oil and Gas Haz Mat Dumpster nearby

**Agencies Involved:**

## ***Updates***

---

***Date:*** 4/23/2013    ***Status:*** Reviewed - Assigned to Other Agency

***Author:*** Roberts, Kris

***Updated Volume:***

***Notes:***

Release apparently occurred on a Whiting O&G location. Will leave this in NDIC hands.